


Cutting rings

TWIN-CUT *supra*



sf
500 Z



PN	$\varnothing \approx D$	L	sf -No.	
L 315	6	9,5	500 Z 6 LS	
	8	10,0	500 Z 8 LS	
	10	10,5	500 Z 10 LS	
	12	10,5	500 Z 12 LS	
	15	10,0	500 Z 15 L	
	18	10,5	500 Z 18 L	
160	22	11,0	500 Z 22 L	
	28	10,5	500 Z 28 L	
	35	13,5	500 Z 35 L	
	42	13,5	500 Z 42 L	
S 630	6	9,5	500 Z 6 LS	
	8	10,0	500 Z 8 LS	
	10	10,5	500 Z 10 LS	
	12	10,5	500 Z 12 LS	
	14	10,0	500 Z 14 S	
	16	10,5	500 Z 16 S	
400	20	13,0	500 Z 20 S	
	25	13,0	500 Z 25 S	
	30	13,5	500 Z 30 S	
315	38	13,5	500 Z 38 S	
250	50	17,0	500 Z 50 S	

Please observe the assembly instructions.